


FUEL SYSTEM/CARBURETION Vent/Fuel Delivery Exploded View

1995 SL650, SL650 STD, SL750 (Early Production)



NOTES:

1. Orient clamps away from oil tank.
2. Verify that all hoses are routed properly and free of kinks and sharp bends.

