
SWIVEL BRACKET BUSHING GREASE PATH

The lubrication path for the swivel bracket bushing has been redesigned affecting the swivel bracket, bushing and shaft. Basically, the grease routing slot located on the clamp bracket shaft has been moved to the clamp bracket bushing.


SWIVEL BRACKET

The swivel brackets have been redesigned from two to only one grease nipple on the port side.




CLAMP BRACKET SHAFT AND BUSHING

The clamp bracket shaft has been redesigned with a clearance hole in place of a slot for routing the grease lubrication.



NOTE:

Install the clamp bracket shaft with "Red" paint marking toward up side.



Download this Manual http://SelfFixer.com